

Provider Number	Nursing Home Name	Street
455061	ELSIE GAYER HEALTH CARE CENTER	902 N MAIN ST
455061	ELSIE GAYER HEALTH CARE CENTER	902 N MAIN ST
455061	ELSIE GAYER HEALTH CARE CENTER	902 N MAIN ST
455061	ELSIE GAYER HEALTH CARE CENTER	902 N MAIN ST
455061	ELSIE GAYER HEALTH CARE CENTER	902 N MAIN ST
455061	ELSIE GAYER HEALTH CARE CENTER	902 N MAIN ST
455691	SHANNON MEDICAL CENTER	2018 PULLIAM
455691	SHANNON MEDICAL CENTER	2018 PULLIAM

Page 1 of 32 05/31/2011



City	State	Zip Code	Phone	Survey Date	Date of Correction
SAN ANGELO	TX	76903	(325) 655-7391	04/17/2008	05/16/2008
SAN ANGELO	TX	76903	(325) 655-7391	05/15/2009	05/30/2009
SAN ANGELO	TX	76903	(325) 655-7391	05/15/2009	05/30/2009
SAN ANGELO	TX	76903	(325) 655-7391	06/10/2010	08/01/2010
SAN ANGELO	TX	76903	(325) 655-7391	06/10/2010	08/01/2010
SAN ANGELO	TX	76903	(325) 655-7391	06/10/2010	08/01/2010
SAN ANGELO	TX	76903	(325) 653-6741	05/20/2009	06/05/2009
SAN ANGELO	TX	76903	(325) 653-6741	02/16/2011	04/15/2011

Page 2 of 32 05/31/2011



	Deficiency Type	Deficiency Category
Fire Safety		Automatic Sprinkler Systems Deficiencies
Fire Safety		Smoke Compartmentation and Control Deficiencies
Fire Safety		Automatic Sprinkler Systems Deficiencies
Fire Safety		Hazardous Area Deficiencies
Fire Safety		Illumination and Emergency Power Deficiencies
Fire Safety		Electrical Deficiencies
Fire Safety		Smoke Compartmentation and Control Deficiencies
Fire Safety		Smoke Compartmentation and Control Deficiencies

Page 3 of 32 05/31/2011



Deficiency	Scope	Level of Harm
properly working sprinkler alarm system.	Widespread	Potential for minimal harm
walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Widespread	Minimal harm or potential for actual harm
properly working alarms on sprinkler valves.	Isolated	Minimal harm or potential for actual harm
construction that can resist fire for one hour or an approved fire extinguishing system.	Pattern	Minimal harm or potential for actual harm
emergency lighting that can last at least 1 1/2 hours.	Widespread	Potential for minimal harm
properly installed electrical wiring and equipment.	Pattern	Minimal harm or potential for actual harm
walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Isolated	Minimal harm or potential for actual harm
walls or barriers that prevent smoke from passing through and would resist fire for at least one hour.	Pattern	Potential for minimal harm

Page 4 of 32 05/31/2011



455691	SHANNON MEDICAL CENTER	2018 PULLIAM
675767	TRISUN CARE CENTER REGENCY HOUSE	3745 SUMMER CREST DR
675767	TRISUN CARE CENTER REGENCY HOUSE	3745 SUMMER CREST DR
675767	TRISUN CARE CENTER REGENCY HOUSE	3745 SUMMER CREST DR
675767	TRISUN CARE CENTER REGENCY HOUSE	3745 SUMMER CREST DR
675767	TRISUN CARE CENTER REGENCY HOUSE	3745 SUMMER CREST DR
675767	TRISUN CARE CENTER REGENCY HOUSE	3745 SUMMER CREST DR
675767	TRISUN CARE CENTER REGENCY HOUSE	3745 SUMMER CREST DR
675767	TRISUN CARE CENTER REGENCY HOUSE	3745 SUMMER CREST DR
675767	TRISUN CARE CENTER REGENCY HOUSE	3745 SUMMER CREST DR
675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR

Page 5 of 32 05/31/2011

tx fire safety Based on Michele A. Williams

SAN ANGELO	TX	76903	(325) 653-6741	02/16/2011	04/15/2011
SAN ANGELO	TX	76901	(325) 947-8776	06/05/2008	06/13/2008
SAN ANGELO	TX	76901	(325) 947-8776	06/05/2008	06/20/2008
SAN ANGELO	TX	76901	(325) 947-8776	06/05/2008	07/15/2008
SAN ANGELO	TX	76901	(325) 947-8776	06/05/2008	06/30/2008
SAN ANGELO	TX	76901	(325) 947-8776	06/05/2008	06/30/2008
SAN ANGELO	TX	76901	(325) 947-8776	07/02/2009	07/31/2009
SAN ANGELO	TX	76901	(325) 947-8776	07/02/2009	07/31/2009
SAN ANGELO	TX	76901	(325) 947-8776	07/02/2009	07/31/2009
SAN ANGELO	TX	76901	(325) 947-8776	07/30/2010	08/13/2010
SAN ANGELO	TX	76903	(325) 653-1266	08/13/2008	09/22/2008

Page 6 of 32 05/31/2011



Fire Safety	Smoke Compartmentation and Control Deficiencies
Fire Safety	Hazardous Area Deficiencies
Fire Safety	Emergency Plans and Fire Drills Deficiencies
Fire Safety	Medical Gases and Anesthetizing Areas Deficiencies
Fire Safety	Electrical Deficiencies
Fire Safety	Electrical Deficiencies
Fire Safety	Emergency Plans and Fire Drills Deficiencies
Fire Safety	Electrical Deficiencies
Fire Safety	Electrical Deficiencies
Fire Safety	Electrical Deficiencies
Fire Safety	Smoke Compartmentation and Control Deficiencies

Page 7 of 32 05/31/2011



smoke barrier doors that can resist smoke for at least 20 minutes.	Pattern	Potential for minimal harm
construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread	Potential for minimal harm
did not have a written emergency evacuation plan.	Widespread	Potential for minimal harm
proper medical gas storage and administration areas.	Widespread	Potential for minimal harm
weekly inspections and monthly testing of generators.	Widespread	Potential for minimal harm
properly installed electrical wiring and equipment.	Widespread	Potential for minimal harm
record of quarterly fire drills for each shift under varying conditions.	Widespread	Potential for minimal harm
weekly inspections and monthly testing of generators.	Widespread	Potential for minimal harm
properly installed electrical wiring and equipment.	Widespread	Potential for minimal harm
properly installed electrical wiring and equipment.	Widespread	Potential for minimal harm
walls or barriers that prevent smoke from passing through and	Widespread	Minimal harm or potential for actual harm

Page 8 of 32 05/31/2011



675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR
675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR
675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR
675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR
675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR
675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR
675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR
675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR
675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR
675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR

Page 9 of 32 05/31/2011



SAN ANGELO	TX	76903	(325) 653-1266	08/13/2008	09/22/2008
SAN ANGELO	TX	76903	(325) 653-1266	08/13/2008	09/22/2008
SAN ANGELO	TX	76903	(325) 653-1266	05/01/2009	05/04/2009
SAN ANGELO	TX	76903	(325) 653-1266	05/01/2009	05/22/2009
SAN ANGELO	TX	76903	(325) 653-1266	05/01/2009	05/22/2009
SAN ANGELO	TX	76903	(325) 653-1266	05/01/2009	05/04/2009
SAN ANGELO	TX	76903	(325) 653-1266	05/01/2009	05/04/2009
SAN ANGELO	TX	76903	(325) 653-1266	05/13/2010	05/14/2010
SAN ANGELO	TX	76903	(325) 653-1266	05/13/2010	05/17/2010
SAN ANGELO	TX	76903	(325) 653-1266	05/13/2010	06/08/2010

Page 10 of 32 05/31/2011



Fire Safety	Automatic Sprinkler Systems Deficiencies
Fire Safety	Automatic Sprinkler Systems Deficiencies
Fire Safety	Corridor Walls and Doors Deficiencies
Fire Safety	Fire Alarm Systems Deficiencies
Fire Safety	Automatic Sprinkler Systems Deficiencies
Fire Safety	Electrical Deficiencies
Fire Safety	Electrical Deficiencies
Fire Safety	Corridor Walls and Doors Deficiencies
Fire Safety	Corridor Walls and Doors Deficiencies
Fire Safety	Smoke Compartmentation and Control Deficiencies

Page 11 of 32 05/31/2011



would resist fire for at least one hour.		
an approved automatic sprinkler system connected to the fire alarm system.	Isolated	Minimal harm or potential for actual harm
automatic sprinkler systems that have been maintained in working order.	Isolated	Minimal harm or potential for actual harm
corridor and hallway doors that block smoke.	Isolated	Minimal harm or potential for actual harm
a fire alarm system that can be heard throughout the facility.	Isolated	Minimal harm or potential for actual harm
automatic sprinkler systems that have been maintained in working order.	Pattern	Potential for minimal harm
weekly inspections and monthly testing of generators.	Widespread	Potential for minimal harm
properly installed electrical wiring and equipment.	Pattern	Potential for minimal harm
corridor and hallway doors that block smoke.	Isolated	Minimal harm or potential for actual harm
signs that state that exit doors are to be kept closed.	Pattern	Potential for minimal harm
smoke barrier doors that can resist smoke for at least 20	Isolated	Minimal harm or potential for actual harm

Page 12 of 32 05/31/2011



675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR
675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR
675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR
675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR
675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR
675932	ARBOR TERRACE HEALTH CARE CENTER	609 RIO CONCHO DR
675982	PARK PLAZA LTC PARTNERS, INC.	2210 HOWARD ST
675982	PARK PLAZA LTC PARTNERS, INC.	2210 HOWARD ST
675982	PARK PLAZA LTC PARTNERS, INC.	2210 HOWARD ST
675982	PARK PLAZA LTC PARTNERS, INC.	2210 HOWARD ST

Page 13 of 32 05/31/2011



SAN ANGELO	TX	76903	(325) 653-1266	05/13/2010	05/25/2010
SAN ANGELO	TX	76903	(325) 653-1266	05/13/2010	05/14/2010
SAN ANGELO	TX	76903	(325) 653-1266	05/13/2010	05/25/2010
SAN ANGELO	TX	76903	(325) 653-1266	05/13/2010	01/01/1900
SAN ANGELO	TX	76903	(325) 653-1266	05/13/2010	06/08/2010
SAN ANGELO	TX	76903	(325) 653-1266	05/13/2010	06/10/2010
SAN ANGELO	TX	76901	(325) 944-0561	09/02/2009	10/05/2009
SAN ANGELO	TX	76901	(325) 944-0561	09/02/2009	10/05/2009
SAN ANGELO	TX	76901	(325) 944-0561	10/12/2010	10/29/2010
SAN ANGELO	TX	76901	(325) 944-0561	10/12/2010	10/29/2010

Page 14 of 32 05/31/2011



Fire Safety	Hazardous Area Deficiencies
Fire Safety	Exits and Egress Deficiencies
Fire Safety	Automatic Sprinkler Systems Deficiencies
Fire Safety	Building Service Equipment Deficiencies
Fire Safety	Medical Gases and Anesthetizing Areas Deficiencies
Fire Safety	Electrical Deficiencies
Fire Safety	Emergency Plans and Fire Drills Deficiencies
Fire Safety	Automatic Sprinkler Systems Deficiencies
Fire Safety	Corridor Walls and Doors Deficiencies
Fire Safety	Hazardous Area Deficiencies

Page 15 of 32 05/31/2011



minutes.		
construction that can resist fire for one hour or an approved fire extinguishing system.	Isolated	Minimal harm or potential for actual harm
exits that are accessible at all times.	Widespread	Potential for minimal harm
an approved automatic sprinkler system connected to the fire alarm system.	Isolated	Minimal harm or potential for actual harm
heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Widespread	Potential for minimal harm
proper medical gas storage and administration areas.	Isolated	Minimal harm or potential for actual harm
properly installed electrical wiring and equipment.	Isolated	Minimal harm or potential for actual harm
did not have a written emergency evacuation plan.	Widespread	Potential for minimal harm
automatic sprinkler systems that have been maintained in working order.	Widespread	Potential for minimal harm
corridor and hallway doors that block smoke.	Isolated	Minimal harm or potential for actual harm
construction that can resist fire	Isolated	Minimal harm or potential for actual

Page 16 of 32 05/31/2011



676031	TRISUN CARE CENTER MEADOW CREEK	4343 OAK GROVE BLVD
676031	TRISUN CARE CENTER MEADOW CREEK	4343 OAK GROVE BLVD
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST

Page 17 of 32 05/31/2011



SAN ANGELO	TX	76904	(325) 949-2559	08/20/2009	09/30/2009
SAN ANGELO	TX	76904	(325) 949-2559	07/01/2010	08/01/2010
SAN ANGELO	TX	76901	(325) 942-0677	12/09/2008	12/10/2008
SAN ANGELO	TX	76901	(325) 942-0677	12/09/2008	12/10/2008
SAN ANGELO	TX	76901	(325) 942-0677	12/09/2008	01/31/2009
SAN ANGELO	TX	76901	(325) 942-0677	12/09/2008	12/10/2008
SAN ANGELO	TX	76901	(325) 942-0677	10/29/2009	12/14/2009
SAN ANGELO	TX	76901	(325) 942-0677	10/29/2009	12/14/2009
SAN ANGELO	TX	76901	(325) 942-0677	10/29/2009	12/14/2009

Page 18 of 32 05/31/2011



Fire Safety	Fire Alarm Systems Deficiencies
Fire Safety	Building Service Equipment Deficiencies
Fire Safety	Hazardous Area Deficiencies
Fire Safety	Automatic Sprinkler Systems Deficiencies
Fire Safety	Automatic Sprinkler Systems Deficiencies
Fire Safety	Electrical Deficiencies
Fire Safety	Corridor Walls and Doors Deficiencies
Fire Safety	Vertical Openings Deficiencies
Fire Safety	Hazardous Area Deficiencies

Page 19 of 32 05/31/2011



for one hour or an approved fire extinguishing system.		harm
properly maintained smoke detectors.	Widespread	Potential for minimal harm
heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Pattern	Potential for minimal harm
construction that can resist fire for one hour or an approved fire extinguishing system.	Widespread	Potential for minimal harm
properly working alarms on sprinkler valves.	Widespread	Minimal harm or potential for actual harm
automatic sprinkler systems that have been maintained in working order.	Widespread	Potential for minimal harm
properly installed electrical wiring and equipment.	Widespread	Potential for minimal harm
corridor and hallway doors that block smoke.	Isolated	Minimal harm or potential for actual harm
exit doors that are held open by devices that will automatically close on the activation of a fire alarm or smoke detectors.	Isolated	Minimal harm or potential for actual harm
construction that can resist fire for one hour or an approved fire	Pattern	Potential for minimal harm

Page 20 of 32 05/31/2011



676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST

Page 21 of 32 05/31/2011



SAN ANGELO	TX	76901	(325) 942-0677	10/29/2009	12/14/2009
SAN ANGELO	TX	76901	(325) 942-0677	10/29/2009	12/14/2009
SAN ANGELO	TX	76901	(325) 942-0677	10/29/2009	12/14/2009
SAN ANGELO	TX	76901	(325) 942-0677	10/29/2009	12/14/2009
SAN ANGELO	TX	76901	(325) 942-0677	10/29/2009	12/14/2009
SAN ANGELO	TX	76901	(325) 942-0677	10/29/2009	12/14/2009
SAN ANGELO	TX	76901	(325) 942-0677	10/29/2009	12/14/2009
SAN ANGELO	TX	76901	(325) 942-0677	10/29/2009	12/14/2009
SAN ANGELO	TX	76901	(325) 942-0677	10/29/2009	12/14/2009
SAN ANGELO	TX	76901	(325) 942-0677	10/29/2009	12/14/2009
SAN ANGELO	TX	76901	(325) 942-0677	09/22/2010	11/15/2010

Page 22 of 32 05/31/2011



Fire Safety	Exits and Egress Deficiencies
Fire Safety	Illumination and Emergency Power Deficiencies
Fire Safety	Emergency Plans and Fire Drills Deficiencies
Fire Safety	Fire Alarm Systems Deficiencies
Fire Safety	Fire Alarm Systems Deficiencies
Fire Safety	Automatic Sprinkler Systems Deficiencies
Fire Safety	Automatic Sprinkler Systems Deficiencies
Fire Safety	Building Service Equipment Deficiencies
Fire Safety	Medical Gases and Anesthetizing Areas Deficiencies
Fire Safety	Electrical Deficiencies
Fire Safety	Hazardous Area Deficiencies

Page 23 of 32 05/31/2011



for one hour or an approved fire extinguishing system.		
exits that are accessible at all times.	Pattern	Minimal harm or potential for actual harm
emergency lighting that can last at least 1 1/2 hours.	Widespread	Minimal harm or potential for actual harm
record of quarterly fire drills for each shift under varying conditions.	Widespread	Minimal harm or potential for actual harm
a fire alarm system that can be heard throughout the facility.	Pattern	Potential for minimal harm
properly maintained smoke detectors.	Widespread	Minimal harm or potential for actual harm
automatic sprinkler systems that have been maintained in working order.	Pattern	Potential for minimal harm
portable fire extinguishers.	Isolated	Minimal harm or potential for actual harm
properly protected cooking facilities.	Isolated	Minimal harm or potential for actual harm
proper medical gas storage and administration areas.	Pattern	Minimal harm or potential for actual harm
properly installed electrical wiring and equipment.	Widespread	Potential for minimal harm
construction that can resist fire	Pattern	Minimal harm or potential for actual

Page 24 of 32 05/31/2011



676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676068	WEST TEXAS LTC PARTNERS INC	1915 GREENWOOD ST
676091	SAGECREST ALZHEIMERS CARE CENTER	438 HOUSTON-HARTE
676091	SAGECREST ALZHEIMERS CARE CENTER	438 HOUSTON-HARTE
676091	SAGECREST ALZHEIMERS CARE CENTER	438 HOUSTON-HARTE
676091	SAGECREST ALZHEIMERS CARE CENTER	438 HOUSTON-HARTE
676100	SENIOR CARE OF SAN ANGELO	5455 KNICKERBOCKER RD

Page 25 of 32 05/31/2011



SAN ANGELO	TX	76901	(325) 942-0677	09/22/2010	11/15/2010
SAN ANGELO	TX	76901	(325) 942-0677	09/22/2010	01/01/1900
SAN ANGELO	TX	76901	(325) 942-0677	09/22/2010	11/15/2010
SAN ANGELO	TX	76903	(325) 486-3702	12/22/2008	01/30/2009
SAN ANGELO	TX	76903	(325) 486-3702	12/03/2009	01/08/2010
SAN ANGELO	TX	76903	(325) 486-3702	11/09/2010	12/20/2010
SAN ANGELO	TX	76903	(325) 486-3702	11/09/2010	12/20/2010
SAN ANGELO	TX	76904	(325) 944-1600	04/10/2009	05/08/2009

Page 26 of 32 05/31/2011



Fire Safety	Automatic Sprinkler Systems Deficiencies
Fire Safety	Building Service Equipment Deficiencies
Fire Safety	Electrical Deficiencies
Fire Safety	Automatic Sprinkler Systems Deficiencies
Fire Safety	Automatic Sprinkler Systems Deficiencies
Fire Safety	Smoking Regulations Deficiencies
Fire Safety	Electrical Deficiencies
Fire Safety	Automatic Sprinkler Systems Deficiencies

Page 27 of 32 05/31/2011



for one hour or an approved fire extinguishing system.		harm
automatic sprinkler systems that have been maintained in working order.	Pattern	Minimal harm or potential for actual harm
heating and ventilation systems that have been properly installed according to the manufacturer's instructions.	Widespread	Potential for minimal harm
properly installed electrical wiring and equipment.	Widespread	Potential for minimal harm
automatic sprinkler systems that have been maintained in working order.	Widespread	Potential for minimal harm
properly working sprinkler alarm system.	Widespread	Potential for minimal harm
posted "No-smoking" signs in areas where smoking is not permitted or did not provide ashtrays where smoking was allowed.	Pattern	Minimal harm or potential for actual harm
properly installed electrical wiring and equipment.	Pattern	Potential for minimal harm
properly working alarms on sprinkler valves.	Pattern	Potential for minimal harm

Page 28 of 32 05/31/2011



676100

SENIOR CARE OF SAN ANGELO

5455

KNICKERBOCKER RD

Page 29 of 32 05/31/2011



SAN ANGELO TX 76904 (325) 944-1600 04/10/2009 05/08/2009

Page 30 of 32 05/31/2011



Fire Safety

Medical Gases and Anesthetizing Areas Deficiencies

Page 31 of 32 05/31/2011



proper medical gas storage and Pattern administration areas.

Potential for minimal harm

Page 32 of 32 05/31/2011